


ANNE KRANAWETTER

CLIENT:

REPORT TO:



11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244 East 11115 Montgomery, Suite B, Spokane, WA 99206-4776 9405 S.W. Nimbus Avenue, Beaverton, OR 97008-7132

(425) 420-9200 FAX 420-9210 (509) 924-9200

(503) 906-9200 (541) 383-9310 FAX 382-7588

924-9290 FAX 906-9210

CHAIN OF CUSTODY REPORT

20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711 Work Order #: *M* INVOICE TO: TURNAROUND REQUEST in Business Days* BRISTOL Organic & Inorganic Analyses 10 4 3 2

AMCHITKA, AK				STD.			<1
PHONE: PROJECTNAME: 70.0974 FAX: 770.0975	P.O. NUMBER:	21000		510.		drocarbon Analyses 2 1 < 1	a
PROJECT NAME: 170.09 14	REQUES	TED ANALYSES		STL			-
PROJECT NUMBER ON CHITICA				1	OTHER	Please Specify	lo
SAMPLED BY: 21090		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		*Turnaro	und Requests less tha	ın standard may incur Rush Ci	7
CLIENT SAMPLE SAMPLING				MATRIX	# OF	sumaara may meur Rush Ci	
IDENTIFICATION DATE/TIME							NCA WO
1. 04 0				(W, S, O)	CONT.	COMMENTS	ID
01 AMTE 06 MT 7/28/01 1010 X				\sim	2		
3.							
4.							
5.							
6.							
7.							
8.						-	
9.							
10.							
11.							
12.							
13.		* * * * * * * * * * * * * * * * * * * *					
14.							
15.							
RELINOUISHED BY:							
PRINT NAME: 2// 1/) +	DATE: 7/28/0	RECEIVED BY:	CANDON R FI			DATE:	7/29/01
PRINT NAME: Who IP the FIRM: BRISTOLE PRINTING BRISTOLE B	TIME: 1630	PRINT NAME:	FAHSAN REL	DOFTERM:UI		TIME:	10:32
PRINT NAME: FIRM:		RECEIVED BY: PRINT NAME:				DATE:	
ADDITIONAL REMARKS:	*900	A ROBERT TRANSPER		FIRM:		TIME:	
OCCREV 3/99 PH= 6.8, turb= 4 NTU, DO= 7.	7 mg/L					TEMP:	
						PAGE	OF
	RETURNING TO A CONTRACTOR OF THE PARTY OF TH	MCDONOMICS CO.					



425.420.9200 fax 425.420.9210

Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776

509.924.9200 fax 509.924.9290

Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132 503.906.9200 fax 503.906.9210

Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711 541.383.9310 fax 541.382.7588

7 December, 2001

Anne Kranawetter Bristol Environmental & Engineering 2000 W International Airport C#1 Anchorage, AK 99502-1116

RE: Amchitka

Enclosed are the results of analyses for samples received by the laboratory on 07/28/01 10:32. If you have any questions concerning this report, please feel free to contact me.

This report was recreated from a previously issued final report in order to provide an electronic copy. The final report used for these electronic copies may have been previously issued as an amended report due to client requested changes to sample names, etc. No data has changed since submission of the previously issued final, or amended, report.

Sincerely,

Stephen Wilson

Environmental Group Leader

112

Work Orders included in this report:

M107055



425.420.9200 fax 425.420.9210

Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776

509.924.9200 fax 509.924.9290 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132

503.906.9200 fax 503.906.9210 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711

541.383.9310 fax 541.382.7588

Bristol Environmental & Engineering 2000 W International Airport C#1

Project Number: 21090

Reported: 07/29/01 11:55

Anchorage, AK 99502-1116

Project Manager: Anne Kranawetter

Project: Amchitka

ANALYTICAL REPORT FOR SAMPLES

Sample ID	Laboratory ID	Matrix	Date Sampled	Date Received
01AMTE06MI	M107055-01	Water	07/28/01 10:10	07/28/01 10:32

COC # 197

North Creek Analytical - Mobile Lab

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.



Anchorage, AK 99502-1116

Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-9223 425.420.9200 fax 425.420.9210

Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776 509.924.9200 fax 509.924.9290

Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132 503.906.9200 fax 503.906.9210

Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711

541.383.9310 fax 541.382.7588

Bristol Environmental & Engineering Project: Amchitka 2000 W International Airport C#1 Project Number: 21090

Reported: 07/29/01 11:55

Polychlorinated Biphenyls per EPA Method 8082

North Creek Analytical - Mobile Lab

Project Manager: Anne Kranawetter

Analyte	Result	Reporting Limit	Units	Dilution	Method	Prepared	Analyzed	Batch	Notes	
01AMTE06MI (M107055-01) Water			Sampled: 07/28/01 Received: 07/28/01							
Aroclor 1016	ND	0.200	ug/l	1	EPA 8082	07/28/01	07/28/01	0107107		
Aroclor 1221	ND	0.400	"	"	"	"	"	"		
Aroclor 1232	ND	0.200	"	"	"	"	"	"		
Aroclor 1242	ND	0.200	"	"	"	"	"	"		
Aroclor 1248	ND	0.200	"	"	"	"	"	"		
Aroclor 1254	ND	0.200	"	"	"	"	"	"		
Aroclor 1260	ND	0.200	"	"	"	"	"	"		
Surr: 2,4,5,6-Tetrachloro-m-xylene	68.0 %	44-119								
Surr: Decachlorobiphenyl	55.0 %	54-128								

North Creek Analytical - Mobile Lab

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.



425.420.9200 fax 425.420.9210

Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776

509.924.9200 fax 509.924.9290

Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132

503.906.9200 fax 503.906.9210

Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711

541.383.9310 fax 541.382.7588

Bristol Environmental & Engineering

Project: Amchitka 2000 W International Airport C#1 Project Number: 21090

Reported: 07/29/01 11:55

Anchorage, AK 99502-1116 Project Manager: Anne Kranawetter

Polychlorinated Biphenyls per EPA Method 8082 - Quality Control

North Creek Analytical - Mobile Lab

		Reporting		Spike	Source		%REC		RPD	
Analyte	Result	Limit	Units	Level	Result	%REC	Limits	RPD	Limit	Notes

Batch 0107107 - 3520B Liq-Liq										
Blank (0107107-BLK1)				Prepared	& Anal	yzed: 07/2	28/01			
Aroclor 1016	ND	0.200	ug/l							
Aroclor 1221	ND	0.400	"							
Aroclor 1232	ND	0.200	"							
Aroclor 1242	ND	0.200	"							
Aroclor 1248	ND	0.200	"							
Aroclor 1254	ND	0.200	"							
Aroclor 1260	ND	0.200	"							
Surr: 2,4,5,6-Tetrachloro-m-xylene	0.149		"	0.200		74.5	44-119			
Surr: Decachlorobiphenyl	0.207		"	0.200		103	54-128			
LCS (0107107-BS1)	LCS (0107107-BS1)			Prepared & Analyzed: 07/28/01						
Aroclor 1254	0.960	0.200	ug/l	1.00		96.0	47-155			
Surr: 2,4,5,6-Tetrachloro-m-xylene	0.159		"	0.200		79.5	44-119			
Surr: Decachlorobiphenyl	0.203		"	0.200		101	54-128			
LCS Dup (0107107-BSD1)				Prepared & Analyzed: 07/28/01						
Aroclor 1254	0.923	0.200	ug/l	1.00		92.3	47-155	3.93	50	
Surr: 2,4,5,6-Tetrachloro-m-xylene	0.117		"	0.200		58.5	44-119			
Surr: Decachlorobiphenyl	0.187		"	0.200		93.5	54-128			
Matrix Spike (0107107-MS1)	Source: M107055-01		Prepared	& Anal	yzed: 07/2	28/01				
Aroclor 1254	0.911	0.200	ug/l	1.00	ND	91.1	50-150			
Surr: 2,4,5,6-Tetrachloro-m-xylene	0.117		"	0.200		58.5	44-119			
Surr: Decachlorobiphenyl	0.145		"	0.200		72.5	54-128			

North Creek Analytical - Mobile Lab

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.



425.420.9200 fax 425.420.9210

Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776

509.924.9200 fax 509.924.9290

Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132 503.906.9200 fax 503.906.9210

Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711 541.383.9310 fax 541.382.7588

Bristol Environmental & Engineering 2000 W International Airport C#1

Project: Amchitka
Project Number: 21090

Reported:

Anchorage, AK 99502-1116

Project Manager: Anne Kranawetter

07/29/01 11:55

Notes and Definitions

DET Analyte DETECTED

ND Analyte NOT DETECTED at or above the reporting limit

NR Not Reported

dry Sample results reported on a dry weight basis. MRLs are adjusted if %Solids are less than 50%.

wet Sample results reported on a wet weight basis (as received)

RPD Relative Percent Difference

North Creek Analytical - Mobile Lab

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Items for Project Manager Review

LabNumber	Analysis	Analyte	Exception
			Report recreated from:
			\\sisters\elmnt\Report\M107055 FINAL 07 29 01
			1155.mdb
			Default Report (not modified)